

Patent No. 7,587,983  
Request for Cert. of Correction dated December 15, 2009  
Attorney Docket No. 5161-045200

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No. : 7,587,983 Application No. 10/508,977  
Inventors : Parker et al. Confirmation No. 1143  
Issued : September 15, 2009  
Title : Drive Mechanism For A Track Mounted Body  
Examiner : Mark T. Le  
Customer No. : 28289

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT  
FOR PTO MISTAKE (37 C.F.R. 1.322(a))

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

ATTENTION: Decision and Certificate of Correction Branch  
Patent Issue Division

Sir:


In accordance with 35 U.S.C. § 254, we attach hereto Form PTO/SB/44 and a copy of proof of PTO errors and request that a Certificate of Correction be issued in the above-identified patent. The following errors appear in the patent as printed:

Face of the Patent, See Item (56), References Cited, U.S. PATENT DOCUMENTS, add the following:

-- 4,467,924 8/1984 Morcheles . . . . . 211/1.5 --  
(See the Examiner's Amendment accompanying the Notice of Allowability, page 8, No. 3. Morcheles is cited in the Examiner's Amendment but was not included on PTO Form 892.

Face of the Patent, See Item (57), ABSTRACT, line 5, "non-load beating" should read -- non-load bearing --  
(See the Examiner's Amendment accompanying the Notice of Allowability, page 8, line 4 of the replacement ABSTRACT.)


Respectfully submitted,  
THE WEBB LAW FIRM

By 

Richard L. Byrne  
Registration No. 28,498  
Attorney for Registrants  
700 Koppers Building  
436 Seventh Avenue  
Pittsburgh, PA 15219  
Telephone: (412) 471-8815  
Facsimile: (412) 471-4094  
E-mail: webblaw@webblaw.com

I certify that this correspondence is being electronically submitted to the United States Patent and Trademark Office on December 15, 2009.

12/15/2009  
Date

  
Signature

Mary Jo Sinicrope  
(Typed Name of Person Signing Certificate)

**UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION**

Page 1 of 1

PATENT NO. : 7,587,983  
APPLICATION NO. : 10/508,977  
ISSUE DATE : September 15, 2009  
INVENTORS : Parker et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Face of the Patent, See Item (56), References Cited, U.S. PATENT DOCUMENTS, add the following:

-- 4,467,924 8/1984 Morcheles . . . . . 211/1.5 --

Face of the Patent, See Item (57), ABSTRACT, line 5, "non-load beating" should read  
-- non-load bearing --

MAILING ADDRESS OF SENDER: The Webb Law Firm  
700 Koppers Building  
436 Seventh Avenue  
Pittsburgh, PA 15219

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-2450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

*If you need assistance in completing the form, call 1-800-PTO-9199 and select Option 2.*